

Repair of EPAL Box pallets

The repair of EPAL Box pallets is only permitted with a valid EPAL licence.

On the day of the evaluation visit, you must have the following work materials and documents:

- proof of at least one valid welder's qualification in accordance with DIN EN ISO 9606-1 (formerly EN 287-1)
- welding equipment
- welding devices
- a riveting machine
- equipment for straightening box pallets
- equipment for painting box pallets (dipping or spray process)
- a paint Thickness measuring instrument
- dimensionally accurate repair materials
- a torque s
- a copy of the UIC 435-3 and UIC 435-4 leaflets
- 20 EPAL Box pallets repaired by you as test samples





THE OPEN PALLET POOL.


EPAL Box Pallet




EPAL Box Pallet (identification plate)



Length view 1.200 mm



Width view 800 mm



Front view

