



The work of the European Pallet Association, its National Committees and licensees forms the stable basis for the successful, open pallet pool and enables the global exchange of EPAL load carriers. The new EPAL 7 half pallet is more robust and longer lasting than the current "Düsseldorfer" half pallet used on the market. The new EPAL 7 half pallets are particularly popular in the drinks and food industry, as well as with discount stores and the retail trade. Constant quality assurance and high quality materials ensure trouble-free, safe performance for users and loading. Their multiple use saves a considerable amount of environmental and economic resources

FACTS & FIGURES

Materials: 13 boards of guality timber, 3 blocks, 42 nails, 6 sturdy 3-mm steel angle brackets, 21 tubular rivets. Produced according to the EPAL Technical Regulations.

Length	800 mm
Width	600 mm
Height	163 mm
Weight	Approx. 9.5 kg
Safe working load	500 kg

When stacking loaded pallets on a firm and level base, the additional load on the bottom-most pallet must not be more than 1,500 kg.

QUALITY CONTROL

The international pool of EPAL load carriers is the only load carrier pool in the world subject to independent quality assurance by external inspection companies. This is the only way for EPAL load carriers to guarantee the consistently high guality that they offer the markets.



ISPM 15

Compliance with the ISPM 15 stan-Ρ dard is the most essential condition Ρ for the unrestricted use of load car-C riers in the international movement of goods. All EPAL load carriers are


therefore produced according to the stringent specifications of the IPPC and can thus be deployed around the globe. Local plant protection agencies will provide information on the countries that recognise the IPPC standard.

HANDLING

handling during production, storage and transportation all the way along the supply chain. Compatible with all (conventional) standard load carriers, industrial trucks and warehouse systems.

4-sided accessibility with chamfered lower edge

boards on both sides enables highly efficient



REPAIR



Damaged EPAL pallets can be repaired cost effectively and in a climate-friendly manner by all EPAL-licensed pallet repair opera-

tions. Following the quality-assured repair, EPAL pallets repaired according to standard receive a repair marking nail bearing the "EPAL" trademark and the licence number of the repair operation.

"EPAL in oval" on the three steel EPA angle brackets on the long side.

MARKINGS


095-3-08 XX-X> 00000 ΗT


IPPC symbol, country code, registration number of the national plant protection authority, heat treatment, licence number-year-month and "EPAL in oval" on the top side of the bottom boards.





600 mm side





Top view

